

# EGÚ - HV LABORATORY

## 190 11 Prague 9 - Běchovice

ACCREDITED TESTING LABORATORY No.: 1029  
Accredited by Czech Accreditation Institute, o.p.s.

**CUSTOMER:**

MEKUFA CZ, s.r.o.  
Ždáňská 477  
685 01 BUČOVICE  
CZECH REPUBLIC

**ORDER No.:**

0202/0019

**DATE OF TEST:**

26<sup>th</sup> September, 7<sup>th</sup>, 8<sup>th</sup> October,  
from 23<sup>rd</sup> till 30<sup>th</sup> October, from 22<sup>nd</sup> till 29<sup>th</sup> November 2002

**TEST No.:**

8800/02

## TEST REPORT

No.: 8800/J/02

**TEST OBJECT:**

ORGANIC INDOOR POST INSULATOR

**PRODUCER:**

MEKUFA CZ, s.r.o.

**TYPE SPECIFICATION:**

10AN

**TEST STANDARD:**

IEC 60660:1999, IEC 60-1:1989

**TEST PERFORMED BY:**

Jan Bolech

**DIRECTOR OF HV LABORATORY:**

Václav Sklenička

COPIES: 4

PAGES: 10 + 1

Test report is confidential and must not be passed over or transferred to any third party without written approval of the customer. Test results relate only to the tests given in presented report and do not substitute any other documents. The report shall not be reproduced except in full without written approval of the testing laboratory.

In Prague 9 - Běchovice: 2002-12-11