## E G Ú - H V L A B O R A T O R Y 190 11 PRAGUE 9 - BĚCHOVICE

ACCREDITED TESTING LABORATORY No.: 1029 Accredited by Czech Accreditation Institute, o.p.s.

CUSTOMER: ORDER No.: MEKUFA CZ, s.r.o. 0202/0019

MEKUFA CZ, s.r.o. Ždáňská 477 685 01 BUČOVICE CZECH REPUBLIC

DATE OF TEST:

26<sup>th</sup> September, 7<sup>th</sup>, 8<sup>th</sup>, from 23<sup>rd</sup> till 30<sup>th</sup> October 2002

8800/02

TECT DEDODT

TEST REPORT

No.: 8800/D/02

TEST OBJECT: ORGANIC INDOOR POST INSULATOR

**PRODUCER:** MEKUFA CZ, s.r.o.

TYPE SPECIFICATION: 20AN

**TEST STANDARD:** IEC 60660:1999, IEC 60-1:1989

TESTING LABORATORY

ARAGUE

No. 1029

TEST PERFORMED BY:

Jan Bolech

**DIRECTOR OF HV LABORATORY:** 

leur

Václav Sklenička

**COPIES: 4 PAGES: 13 + 2** 

Test report is confidential and must not be passed over or transferred to any third party without written approval of the customer. Test results relate only to the tests given in presented report and do not substitute any other documents. The report shall not be reproduced except in full without written approval of the testing laboratory.

Im Prague 9 - Běchovice: 2002-10-31